

Er. J.V PRASAAD  
BE, PGDCM, C. ENG. (I), FIV  
MICA, MIE, M.I.STRUCT.E  
CHARTERED ENGINEER,  
APPROVED ENGINEER BY P.W.D & N COLLECTOR'S PANEL  
ISSUE BUILDING STRUCTURAL STABILITY CERTIFICATE

No.18/22, Thiruvalluvar Street,  
Subramanya Nagar,  
Tiruttani – 631209.  
Cell No.94433 79267, 99623 99199,  
Phone No.04177 - 27886749  
(Mail : jvprasaad@gmail.com)

**STATEMENT ACCOMPANYING FORM 'A'**

1. Name of the School : **SHAKTHI PUBLIC SCHOOL.,**
2. Location / Name of the Place : (As Informed / Reported),  
Name of place, I.e. Corporation : S.F.No.167/2,Tiruttani to Thirupathi Road,  
Municipality / Panchayat. : Murukkampattu Village,  
Tiruttani Taluk,Tiruvallur District.
3. Year of construction : **GF & FF – RCC – 2011 – 7 Years,**  
**SF – RCC – 2014 – 3 Years**
4. Purpose for which the building is : For conducting School classes  
Being used or proposed to be used
5. Purpose for which the building has : For Conducting School classes  
Hitherto been used
6. Details of construction of the building :  
(Particulars) of the foundation, soil  
Specification of the various parts as under
  - a. Foundation : RCC Isolated Footings
  - b. Basement : Brick Work in C.M
  - c. Superstructure- : Columns, Beams Brick Work With CM
  - d. Flooring & Roof, are to be given : RCC Roof, Flooring – Granite & Tiles Flooring.
7. Period for which license is required : **From 02.06.2017 to 01.06.2020**
8. Number of persons to be accommodated : **About 1000 Pupils**  
(One Thousand Pupils Only)

Place : Tiruttani.

Dated: 31.05.2017.



Er. J.V PRASAAD

BE, PGDCM, C. ENG. (i), FIV

MICA, MIE, M.I.STRUCT.E

CHARTERED ENGINEER,

APPROVED ENGINEER BY P.W.D & N COLLECTOR'S PANEL

ISSUE BUILDING STRUCTURAL STABILITY CERTIFICATE

No.18/22, Thiruvalluvar Street,

Subramanya Nagar,

Tiruttani – 631209.

Cell No.94433 79267, 99623 99199,

Phone No.04177 - 27886749

(Mail : jvprasaad@gmail.com)

ANNEXURE TO "STATEMENT ACCOMPANYING FORM – A "

We have inspected the School building of **SHAKTHI PUBLIC SCHOOL**, (As Informed / Reported), S.F.No.167/2,Tiruttani to Thirupathi Road, Murukkampattu Village, Tiruttani Taluk, Tiruvallur District. The following Building is of. **GF & FF – RCC – 2011 – 7 Years, SF – RCC – 2014 – 3 Years**. Said One Block is Available. This Report does not include any other Buildings/ Blocks or Structures Such as Compound wall, OHT, Sump, Septic tank, Security Cabin, Semi / Non Permanent Structures either in GF and any other Floors and etc. Will not cover in this report. We Here by advice that The Periodical Repairs and Renovations shall be Carried Out to the Entire Building Blocks regularly.

Further Necessary fire fighting equipments should be kept in the premises and should be trained for operation. If any fire accident / Mishap occur we are not held responsible. Emergency Exit to be provided as per norms. Structural Alteration / Deviation Should Not be carried out to any of The blocks for Whole Building Or any Part With out Prior Permission from the Competent Authority. All electrical points, wiring / Gadgets has to be checked properly and to be maintained regularly. Weathering course has to be laid, Terrace / Roof water Drain pipes to be replaced and new has to be provided to avoid Dampness / Leakage. Whenever Dampness arises in walls / Roofs has to be arrested immediately by water proofing treatment as per IS standards. It is strictly advised to make the Repairs to All the / Air Cracks immediately. **This Report does not cover any Structure / Partly completed / Building under construction. Any further additional construction either in G.F, or in any other Floors / Blocks the necessary approvals / structural design has to obtained from competent authority.All Necessary Safety standards has to be Strictly adhered.** All Electrical Panel Boards/Main Switches / cables, Generator, Electrical Maintenance Room Gen Room has to be kept in safety with lock & key position. Electrical conduits / Cables should not be loosely run on the open ground, it has to be put in Cable Tranches and covered slabs. All the manual I Man holes cover has to be closed. Access to open terraces to be kept in Lock & key Position. The UG sump, manholes, OHT, Inspection Chamber, septic Tank Openings as to be Sealed with cover slab. Legal Aspects were not considered in this report. Further if any above mentioned Aspects were Found violated at a later date after issue of this Report / License we are not held responsible and this Report gets cancelled.

Place: Tiruttani.

Date: 31.05.

2017.



**FORM – B**

**STATEMENT TO ACCOMPANY THE REPORT OF STRUCTURAL SOUNDNESS**

Location of the Building door No. Street Name & Name of the Place	Age of the Building	No of storey's	Short Description of structure, steel RCC framed or load bearing masonry.
---	---------------------	----------------	---

**SHAKTHI PUBLIC SCHOOL,,**

(As Informed / Reported),

S.F.No.167/2,Tiruttani to Thirupathi Road,

Murukkampattu Village,

Tiruttani Taluk, Tiruvallur District.

**GF & FF – RCC – 2011 – 7 Years, SF – RCC – 2014 – 3 Years.**

RCC Isolated Footings

Brick Work in C.M

Columns, Beams, Brick Work With CM

RCC Roof, Flooring – Granite & Tiles Flooring

Purpose for which The building to be used	Period for which the license is required	No. of persons accommodated.	Remarks
---	--	------------------------------	---------

For conducting School Classes **02.06.2017 to 01.06.2020** About 1000 Pupils. (One Thousand Pupils Only)

**FOR THREE YEARS ONLY** This Report does not include any Eventualities caused by Natural Calamities. This Report Does not include any Eventualities caused by Natural Calamities. We here by advise that the Periodical Repairs and Renovations Shall be carried out to the Entire Building Block regularly. Further Necessary firefighting equipment's should be kept in the premises and should be trained for operation. If any fire accident / Mishap occurs we are not held responsible. Structural Alteration / Deviation Should Not be carried out to a part / whole Building without Prior Permission from the Competent Authority. Emergency Exit to be provided as per norms. All electrical points, wiring / Gadgets has to be checked properly and to be maintained periodically. Access to open terraces to be kept in Lock & key Position. The UG sump, manholes, OHT, Inspection Chamber, septic Tank Openings as to be Sealed with cover slab. **All Necessary safety standards has to be strictly adhered.** If any violations is found at a later period after issue of this Report / License we are not held responsible and this Report gets cancelled. **Further this Report covers the above said Building Blocks Only. Legal Aspects were not considered in this Report**

Place : Tiruttani.

Dated : 31.05.2017.



**FORM – C**

Form of Report of structural soundness under sub-section (4) of section 4 of The Tamil Nadu public building (licensing) Act 1965 (Tamil Nadu act 1 of 1965) Referred to in rule 4 of the Tamil Nadu public (Licensing) Rules, 1966.

We have inspected the building Blocks of above Said School on .09.05.2017. Mentioned in the statement and furnish below its salient technical features:

**1. Foundation:**

- a. Depth below ground level : About 1. 80 Mts
- b. Nature of soil met with at Foundation level. : Red & Gravel Mixed Soil
- c. Pressure at foundation :
- d. Probable safe bearing capacity of The soil strata met with at foundation : About 180 KN / Sq.m

**2. Superstructure :**

- a. Maximum stress in the most Critical section of Masonry and concrete : Brick Masonry in Cement Mortar
- b. Nature of masonry and concrete : And its safe permissible stress

We are of the Opinion that the above said Building – Subject Block may be used for public purpose. It is of Structurally Sound [subject to Remarks]. A license may be granted for the period from **02.06.2017 to 01.06.2020 (FOR THREE YEARS ONLY)**

Place: Tiruttani.

Date : 31.05.2017.



K.Dis No.935/2021/A1, Dated 14.07.2021

Taluk Office,  
Tiruttani.

**FORM - D**


FORM OF LICENCE UNDER SUB - SECTION (1) OF SECTION (6) OF THE TAMIL NADU PUBLIC BUILDING (LICENSING) ACT 1985 (TAMIL NADU ACT 13 OF 1963) REFERED TO IN RULE 6 OF THE TAMIL NADU PUBLIC BUILDINGS (LICENSING RULES 1966)

LICENCE NO. 06/2021

LICENCE FEE OF Rs.1500/-  
(One Thousand Five Hundred Only)  
Challan No.12 , Remitted on : 13.07.2021  
State Bank of India, Tiruttani.


LICENCE is hereby granted to the **M/s. Shakthi Public School, Murukkampattu Village, Tiruttani Taluk, Tiruvallur District**, for the purpose and respect of the building specified in the statement below and subject to the conditions and for the period mentioned.

1. The period of Validity of the License shall be from **05.07.2021 to 04.07.2024**.
2. The building shall be utilized only for the purpose of school in column (2) below.
3. The number of persons to be accommodation should not exceed the number specified in column (3) below.

  
TAHSILDAR,  
TIRUTTANI.


**COMPLETENT AUTHORITY STATEMENT OF ACCOMPANY THE LICENCE**

Location of the building Door No. Street No and Name of Place	Purpose for which the building to be used as a public Building	Number of persons can be accommodated
M/s. Shakthi Public School, Murukkampattu Village, Tiruttani Taluk, Tiruvallur District. Survey No.167/2A1	For School Purpose	1000

  
TAHSILDAR,  
TIRUTTANI.

To

M/s. Shakthi Public School,  
Murukkampattu Village,  
Tiruttani Taluk,  
Tiruvallur District.



  
14/7/2021